

BE (Civil), M.Sc. (Real Estate), F.I.V., F.I.E. Registered Valuer of Govt. of India For Income Tax & Wealth Tax & Valuer for Banks

RESIDENCE -CUM- OFF:

H/No. 1470, Sector 13, HUDA, Bhiwani Rajeev Kumar { 9315447057

9255414430

Email : rajeevjuneja70@gmail.com

Gurugram Off. : Flat No. 304, EWS, 3rd Ploor, Takshilla Heights, Sector-37C, Gurugram.

Delhi-Resi./Off. : KP-328, Maurya Enclave, Pitampura New Delhi-110034

Rohtak Office Shop No. 16. Shahid Bhagat Singh Marke Choumin Chowk, Circular Road, Rohtak

Annexure D

Dated ... 1.1.9 20 Al

BUILDING SAFETY CERTIFICATE

Dated: 11/09/2024

It is certified that this existing building for triple storey Sr. Sec. School namely ADARSH VIDYA MANDIR SR. SEC. SCHOOL, at mouja Paluwas Teh. & Distt. Bhiwani is having block(s) / Floor(s) as per details below:

Detail of Block(s) in School	Block	Block	Block	Block	Block	Block
	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor (s) in the Block	3				,	and the second s

The building is owned / occupied by Adarsh Education and Welfare Society Indra Colony Bhiwani having Regd no. HR013-2013-00173 Dated 18/06/2013 & School affiliation with authority is valid up to 31/03/2027, have complied with the Building safety requirements in accordance with National Building code Rules-2005, & verified by the officers concerned of Sh. Rajiv Kumar approved Structural Engineer Regd. with HUDA Hisar (Name of Department / Govt.) on 10/09/2024 (date of inspection) in the presence of Sh. Shamsher Singh (Secretary) of Society (name and addresses of the Manager / Secretary or his representative) and that the building / premises is fit for occupancy & running school with effect from 11/09/2024 to 10/09/2027 for a period of 3 years in accordance with rule and subject to compliance of the specific conditions as appended.


- 1. The building was constructed by Society in year 2015-2017 i.e app. 8 years old
- 2. Entire building is in form of single block as in form of triple storey for Sr. Sec. School
- 3. The building is main RCC framed structure constructed as per NDMA-2005 norms and very maintained
- 4. With all above points is very maintained, structurally quite safe against all types of loads viz. Seismic, Live and dead load.

















REGUL NO.: 1411



RAIIV KUMAR

BE (Civil), M.Sc. (Real Estate), F.I.V., F.I.E. Registered Valuer of Govt. of India For Income Tax & Wealth Tax & Valuer for Banks

RESIDENCE-CUM-OFF:

H/No. 1470, Sector 13, HUDA, Bhiwani

Rajeev Kumar { 9315447057 9255414430

Email: rajeevjuneja70@gmail.com

Gurugram Off.: Flat No. 304, EWS, 3rd Ploor, Takshilla Heights, Sector-37C, Gurugram. Delhi Resi./Off.: KP-328, Maurya Enclave, Pitampura New Delhi-110034 Rohtak Office : Shop No. 16, Shahid Bhagat Singh Marke Choumin Chowk, Circular Road, Rohtak

Ref. No. 182/13414/05/24-25

Dated 11 9 20214

Finally, I am of result that building is quite safe for further 52 to 53 years Issued on 11/09/2024 at

9:35 A.M by.

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Name: Rajiv Kumar

Designation: Structural Engineer

Name & Address of Department/ Office: HUDA